

Dart Aerospace Ltd. Monday, 5/14/2007 7:15:02 AM Date Kim Johnston **Process Sheet** User: : HARNESS ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer : 32337 Job Number : 12859 **Estimate Number** : D412702111B Part Number 5/14/2007 P.O. Number ICA D412-702 P.79 **Drawing Number** S.O. No. : NIA This Issue N/A Project Number Prsht Rev. : D SMALL /MED FAB **Drawing Revision** Type First Issue : NIA Material **Previous Run** Each : 5/15/2007 **Due Date** Written By Checked & Approved By est rev A 0105.11 new issue EC Comment **Additional Product** Job Number: Description: Machine Or Operation: Seq. #: DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL type labels per PPP D412-702-111B CHG001 BRACKET 2.0 D35701 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) BRACKET batch: 12 1866 SHOULDER HARNESS LH 3.0 D3579047 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) SHOULDER HARNESS RH batch: B 32116 4.0 MS24694S50 Screw Comment: Qty.: 4.0000 Each(s)/Unit Total: 40.0000 Each(s) Screw 114206 batch: AN960JD10I Washer 5.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 40.0000 Each(s) Washer batch: /

Monday, 5/14/2007 7:15:02 AM Date: Kim Johnston **Process Sheet** User: Drawing Name: HARNESS ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412702111B Job Number: 32337 Job Number: Description: Seq. #: Machine Or Operation: MS21042L3 6.0 40.0000 Each(s) 4.0000 Each(s)/Unit Total: Comment: Qty: Nut 103641 batch: D35693 7.0 10.0000 Each(s) Comment: Qty: 1.0000 Each(s)/Unit Total: **DECAL** batch: 3208C SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 8.0 07/05/16 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per dwg ICA D412-702 p.79 INSPECT WORK TO CURRENT STEP 9:0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 10.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-702-111B CHG001 Location: PPP Rev. Job Completion



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS. K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



SHOP COPY RETURN TO ENGINEERING

DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIESUNCONTROLLED COPY SUBJECT TO AMENDMENT (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

WITHOUT NOTICE

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

Page 49 (50 blank) of 68

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By Date	Qty	Approval Chief Eng / Prod Migr Approval QC Inspector			
105/17		W/o split again	07/05/17	2	6705-17 BOS-17			

Part No: _	PAF	R#: Fault Cate	gory: NCR: \	Yes (No) DQA: =	1) Date: <u>07/05/1</u> 7
				A. N/C Closed:	Data

NCR:			WORK OR	DER NON-CONFORMANCE	E (NCR)			
DATE	STEP	Description of NC Section A		Corrective Action Section B			Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	Approval QC Inspector
٨		label D3569-3	re	Use Contact Ciment M102565	mli		VE	
W) 17	8	label D3569-3 do not stick	67.05.17		07/05/17		07.05.17	//
				M102565		AUS:17		0
				SEE W/O 32332 FOX EMAIL				905.17
				·				<u> </u>
								į.
							·	
1 .								

NOTE: Date & initial all entries